


PPMS1 WIRING DIAGRAM

V3 OCT 2021



See also: Page A-12 of the PPMS manual for details of the connections from the sample connector at the bottom of the chamber to the grey Lemo connector on the probe head and the P1 User bridge connector on the Model 6000 bridge