


# PPMS1 WIRING DIAGRAM



Note: probes or kits shipped prior to May 2019 may use coloured heat shrink to identify 4-pin connectors on the puck (blue = 1, brown = 2, black = 3)

See also: Page A-12 of the PPMS manual for details of the connections from the sample connector at the bottom of the chamber to the grey Lemo connector on the probe head and the P1 User bridge connector on the Model 6000 bridge